





## MAIN FEATURES

Complete group made of load cell and electronic weight indicator, mainly used in laboratory tests.

Display indications: weight (6 digit) Tare zero and weight settings. Measuring units selection (kg - t - N - kN). Automatic power-off when rising above the range Digital filter selection.

Peak function (it visualizes and hold the maximum weight). Automatic transmission via RS232 of the measured weight. Selection of the automatic auto-zero at power-on





Capacity	Division
kg	g
6	2
15	5
30	10
60	20
150	50
300	100
600	200